

Tech Brief 01-08-021

Reverse Engineering Track Components



Traditional Method:

model or drawings.

Problem:

Taking hand measurements and using patterns to capture complex geometry is time consuming and can be inaccurate.

The manufacturing process for disposable

lighters entails the use of an extensive array of automated machinery. Over time, many components wear, and must be replaced. Most of these components have no CAD

NeoMetrix Solution:

- Track Assembly scanned in house with Range 7 scanner. (Accuracy of .0015")
- Scan Data is registered, merged, and aligned in Rapidform XOR. (Figure 2)
- Solid model created in Rapidform XOR to match scan data. (Figure 3)



Figure 2 - Scan Data

Figure 3 – Completed model

NeoMetrix Advantage:

- Complex geometries accurately recreated using parametric modeling functions.
- File available in IGES, STEP, and Parasolid formats for milling or mold creation.
- Solidworks and Pro/Engineer files also available with history tree for design changes preceding production.